






GM-SL

Data Interface module self-learning for Security System and / or Remote Starter.
(Self Learning)



Vehicles	Years	PK3, Bypass or PK3 VATS	Bypass Control	Factory Alarm Control (OEM)	Trunk Release	Dome Light (Supervising)	Heated and Mirror	Heated Seat	Defrost	Rear Parking Control	accessory power	RAP Radio (by Unlock)	Memory selection Driver 1 and 2
Bravada	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Envoy	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
TrailBlazer	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Rainier	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Avalanche	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Escalade	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
C/K Pick Up	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Silverado	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Sierra	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Suburban	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Tahoe	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Yukon (All models)	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Hummer H2	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Aurora	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Deville	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Le Sabre	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Bonneville	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Park Avenue	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
SRX	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
SLS	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
CTS	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
STS	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
EXT	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Alero	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Astro & Safari	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Blazer	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Cavalier & Sunfire	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Express & Savana	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Grand Am	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Impala&MonteCarlo	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Intrigue	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Sonoma & S-10	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Colorado	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Canyon	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Saturn Série S	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Saturn ION	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Aztek	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Grand Prix	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Montana	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Venture	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Rendez-vous	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Silhouette	98 99 00 01 02 03 04 05 06	X	•	•	•	•	•	•	•	•	•	•	•
Relay	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Terraza	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
SV6 & Uplander	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Corvette	98 99 00 01 02 03 04 05 06	?	•	•	•	•	•	•	•	•	•	•	•
Century	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•
Hummer H3	98 99 00 01 02 03 04 05 06	•	•	•	•	•	•	•	•	•	•	•	•

PROGRAMMING SEQUENCE :

- Locate and press the programming switch while inserting the wire harness into connector 1 of the GM-SL module. The LED status indicator will illuminate to indicate you are in programming mode. Keep the programming button pressed while turning the ignition to the "ON" position. Release the programming switch once the LED status indicator flashes rapidly.
- Start the engine (using the key). The LED status indicator will turn off to indicate the module has been programmed. Turn the key to the "OFF" position. The module is now ready for use.

Special programming available on technical support internet site at <http://support.fortinautoradio.com> select GM-SL and installation manuals (Special Programming).

Neither the manufacturer or distributor of this module is responsible of damages of any kind indirectly or directly caused by this module, except for the replacement of this module in case of manufacturing defects. This module must be install by qualifier technician.

Technical Support :
TEL: 514-255-0446 FAX: 514-255-1367
Web: <http://support.fortinautoradio.com>

Parts No. : GM-SL
Version : 2.2.C
Revision : Oct.. 18 2005
Made in Canada

Manufacturé sous brevet US No.:
5,719,551 6,011,460 B1
6,243,004 B1 6,249,216 B1
6,275,147 B1 6,529,124 B2
6,696,927 B2 6,756,885 B1
6,756,886 B2 6,771,167 B1
Brevet Canadien No.:
2,320,248 2,415,023
Brevet Européen No.:1,053,128

X : Bypass Passlock or PK3 only
? : Not TESTED on all series of each models, but should be functional.
★ : Functional with 12V ignition only
Note : Heated seat will turn ON at low power ONLY if the engine temp is below 0° when it started.